

Page 1/8

## **Safety Data Sheet** acc. to OSHA HCS

Printing date 10/01/2020

Reviewed on 11/16/2017

- **1** Identification
- · Product identifier
- Trade name: Elevate Imaging Compatible Replacement Toner Cartridge for: HP® CE400X (BLACK)
- · Article number: AHWE4001C0N
- · Application of the substance / the mixture Printing inks
- · Details of the supplier of the safety data sheet
- · Manufacturer/Supplier: Static Control Components Inc.
- P.O. Box 152 Sanford, North Carolina, 27331 info@scc-inc.com
- · Information department: Product Safety Department · Emergency telephone number: During Normal Operating Hours: 919-774-3808 Emergency Telephone Number: 1-919-770-7984 or 1-919-770-6019

# 2 Hazard(s) identification

#### · Classification of the substance or mixture

- Combustible Dust May form combustible dust concentrations in air.
- · Label elements
- · GHS label elements The product is classified and labeled according to the Globally Harmonized System (GHS).
- · Hazard pictograms Void
- · Signal word Warning
- · Hazard statements
- May form combustible dust concentrations in air.
- · Classification system:
- · NFPA ratings (scale 0 4)



### · HMIS-ratings (scale 0 - 4)

HEALTH 1	Health = 1
FIRE 1	Fire = 1
REACTIVITY 0	Reactivity $= 0$

- · Other hazards
- · Results of PBT and vPvB assessment
- **PBT:** Not applicable.
- **vPvB:** Not applicable.

## **3** Composition/information on ingredients

- · Chemical characterization: Mixtures
- · Description: Resin mixture

(Contd. on page 2)



Page 2/8

Safety Data Sheet acc. to OSHA HCS

Printing date 10/01/2020

Reviewed on 11/16/2017

### Trade name: Elevate Imaging Compatible Replacement Toner Cartridge for: HP® CE400X (BLACK)

	(Contd. of page 1)
· Dangerous components:	
1333-86-4 Carbon black (bound)	>2.5-≤10%
8002-74-2 Paraffin waxes and Hydrocarbon waxes	>2.5-≤10%
· Non-hazardous components	
25085-34-1 Polymer	>50-≤100%
7631-86-9 silicon dioxide, chemically prepared	>2.5-≤10%

## **4 First-aid measures**

· Description of first aid measures

- · General information: No special measures required.
- After inhalation: Supply fresh air; consult doctor in case of complaints.
- · After skin contact:

Immediately wash with water and soap and rinse thoroughly.

- Generally the product does not irritate the skin.
- · After eye contact: Rinse opened eye for several minutes under running water. If symptoms persist, consult a doctor.
- · After swallowing: Drink copious amounts of water and provide fresh air. Immediately call a doctor.
- · Information for doctor:
- · Most important symptoms and effects, both acute and delayed No further relevant information available.
- · Indication of any immediate medical attention and special treatment needed No further relevant information available.

## **5** Fire-fighting measures

- · Extinguishing media
- Suitable extinguishing agents: Use fire fighting measures that suit the environment.
- · For safety reasons unsuitable extinguishing agents: No Information Available
- · Special hazards arising from the substance or mixture
- Like most finely divided organic powders, toner dust may form an explosive mixture in air.
- · Advice for firefighters
- · Protective equipment: Wear self-contained respiratory protective device.

# **6 Accidental release measures**

- · Personal precautions, protective equipment and emergency procedures
- Wear protective equipment. Keep unprotected persons away.
- · Environmental precautions: No special measures required.
- $\cdot$  Methods and material for containment and cleaning up:

Vacuum or sweep the material into a sealed container. If a vacuum is used it must be dust explosion-proof. Dispose of in compliance with national, state, regional or provincial regulations.

- · Reference to other sections
- See Section 7 for information on safe handling.
- See Section 8 for information on personal protection equipment.
- See Section 13 for disposal information.

(Contd. on page 3)



Page 3/8

## Safety Data Sheet acc. to OSHA HCS

Printing date 10/01/2020

Reviewed on 11/16/2017

## Trade name: Elevate Imaging Compatible Replacement Toner Cartridge for: HP® CE400X (BLACK)

(Contd. of Protective Action Criteria for Chemicals	
• PAC-1:	
1333-86-4 Carbon black (bound)	9 mg/m <sup>3</sup>
7631-86-9 silicon dioxide, chemically prepared	18 mg/m <sup>3</sup>
· PAC-2:	
1333-86-4 Carbon black (bound)	99 mg/m <sup>3</sup>
7631-86-9 silicon dioxide, chemically prepared	740 mg/m <sup>3</sup>
· PAC-3:	
1333-86-4 Carbon black (bound)	590 mg/m <sup>3</sup>
7631-86-9 silicon dioxide, chemically prepared	4,500 mg/m <sup>3</sup>

# 7 Handling and storage

· Handling:

- · Precautions for safe handling
- No special measures required.
- Store in cool, dry place in tightly closed receptacles.
- Keep away from heat and direct sunlight.
- No special precautions are necessary if used correctly.
- Use only in well ventilated areas.
- · Information about protection against explosions and fires: Keep ignition sources away Do not smoke.
- · Conditions for safe storage, including any incompatibilities
- · Storage:
- **Requirements to be met by storerooms and receptacles:** Store in a cool location. Store only in the original receptacle.
- Information about storage in one common storage facility:
- Do not store together with oxidizing and acidic materials as well as heavy-metal compounds.
- · Further information about storage conditions:
- Store in cool, dry conditions in well sealed receptacles.
- Protect from heat and direct sunlight.
- Protect from humidity and water.
- Specific end use(s) No further relevant information available.

# 8 Exposure controls/personal protection

- · Additional information about design of technical systems: No further data; see item 7.
- · Control parameters

· Components with limit values that require monitoring at the workplace:

- 1333-86-4 Carbon black (bound)
- PEL Long-term value: 3.5 mg/m<sup>3</sup>

(Contd. on page 4)



Safety Data Sheet acc. to OSHA HCS

Printing date 10/01/2020

Reviewed on 11/16/2017

# Trade name: Elevate Imaging Compatible Replacement Toner Cartridge for: HP® CE400X (BLACK)

REL       Long-term value: 3.5* mg/m³         *0.1 in presence of PAHs;See Pocket Guide Apps,A+C         TLV       Long-term value: 3* mg/m³         *inhalable fraction         8002-74-2 Paraffin waxes and Hydrocarbon waxes         REL       Long-term value: 2 mg/m³         TLV       Long-term value: 2 mg/m³         *Additional Occupational Exposure Limit Values for possible hazards during processing:         USA OSHA (TWA/PEL): 15 mg/m3 (Total Dust), 5 mg/m3 (Respirable Fraction)         ACGIH (TWA/TLV): 10 mg/m3 (Inhalable Particulate), 3 mg/m3 (Respirable Particulate)         Amorphous Silica:       USA OSHA (TWA/PEL): 20mppef 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3         TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion)         UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust)         • Additional information: The lists that were valid during the creation were used as basis.         • Exposure controls         • Personal protective equipment:         • General protective equipment:         • General protective and bygienic measures:         Wash hands before breaks and at the end of work.         Do no tinhale dust 's moke / mist.         • Protection of hands:         Selection of the suitable gloves does not only depend on the material, but also on further marks of quality and from staney fusterial         The exact b		(Contd. of page
TLV       Long-term value: 3* mg/m³         *inhalable fraction         8002-74-2 Paraffin waxes and Hydrocarbon waxes         REL       Long-term value: 2 mg/m³         *Additional Occupational Exposure Limit Values for possible hazards during processing:         USA OSHA (TWA/PEL): 15 mg/m3 (Total Dust), 5 mg/m3 (Respirable Fraction)         ACGIH (TWA/TLV): 10 mg/m3 (Inhalable Particulate), 3 mg/m3 (Respirable Particulate)         Amorphous Silica:       USA OSHA (TWA/PEL): 20mppef 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3         TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion)         UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust)         Additional information: The lists that were valid during the creation were used as basis.         Exposure controls         Personal protective equipment:         General protective and hygienic measures:         Wash hands before breaks and at the end of work.         Do no tinhale dust / smoke / mist.         Protection of hands:         Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation         Material of gloves         The selection of the agit the has to be found out by the manufacturer of the protective gloves and has to be observed         Eye protection:         Physical and chemical propertics         Ceneral Information		Pocket Guide Apps A+C
*inhalable fraction         8002-74-2 Paraffin waxes and Hydrocarbon waxes         REL       Long-term value: 2 mg/m³         TLV       Long-term value: 2 mg/m³         Additional Occupational Exposure Limit Values for possible hazards during processing:         USA OSHA (TWA/PEL): 15 mg/m3 (Total Dust), 5 mg/m3 (Respirable Fraction)         ACGIH (TWA/TLV): 10 mg/m3 (Inhalable Particulate), 3 mg/m3 (Respirable Particulate)         Amorphous Silica:       USA OSHA (TWA/PEL): 20mppef 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3         TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion)         UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust)         Additional information: The lists that were valid during the creation were used as basis.         Exposure controls         Personal protective equipment:         General protective and bygienic measures:         Wash hands before breaks and at the end of work.         Do not inhale dust / smoke / mist.         Protection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves         The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed Exe protection: Safety glasses         Physical and chemical properties         General Information on basic physical and chemical properties         General Information Optical and chemical pr	-	Pocket Guide Apps.A+C
8002-74-2 Paraffin waxes and Hydrocarbon waxes         REL       Long-term value: 2 mg/m³         Additional Occupational Exposure Limit Values for possible hazards during processing:         USA OSHA (TWA/PEL): 15 mg/m3 (Total Dust), 5 mg/m3 (Respirable Fraction)         ACGIH (TWA/TLV): 10 mg/m3 (Inhalable Particulate), 3 mg/m3 (Respirable Particulate)         Amorphous Silica:       USA OSHA (TWA/PEL): 20mppef 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3         TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare particle)). 3 mg/m3 (Alveolengängige fraktion)         UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust)         Additional information: The lists that were valid during the creation were used as basis.         Exposure controls         Personal protective equipment:         General protective equipment:         General protective equipment:         Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation         Material of gloves         The selection of the glove material         The selection of the gloves does not only depend on the material, but also on further marks of quality and from manufacturer.         Penetration fine of glove material         The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed         Eye protection:         Salex         Oclor:       Powder		
REL       Long-term value: 2 mg/m³         TLV       Long-term value: 2 mg/m³         Additional Occupational Exposure Limit Values for possible hazards during processing:         USA OSHA (TWA/PEL): 15 mg/m3 (Total Dust), 5 mg/m3 (Respirable Fraction)         ACGIH (TWA/TLV): 10 mg/m3 (Inhalable Particulate), 3 mg/m3 (Respirable Particulate)         Amorphous Silica:       USA OSHA (TWA/PEL): 20mppcf 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3         TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion)         UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust)         Additional information: The lists that were valid during the creation were used as basis.         Exposure controls         Personal protective equipment:         General protective and hygienic measures:         Wash hands before breaks and at the end of work.         Do not inhale dust / smoke / mist.         Protection of hands:         Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation         Material of gloves         The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed         Eye protection: Safety glasses         Physical and chemical properties         General Information         Appearance:         Form:       Powder		rocarbon waxes
TLV       Long-term value: 2 mg/m <sup>3</sup> Additional Occupational Exposure Limit Values for possible hazards during processing:         USA OSHA (TWA/PEL): 15 mg/m3 (Total Dust), 5 mg/m3 (Respirable Fraction)         ACGIH (TWA/TLV): 10 mg/m3 (Inhalable Particulate), 3 mg/m3 (Respirable Particulate)         Amorphous Silica: USA OSHA (TWA/PEL): 20mppef 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3         TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion)         UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust)         Additional information: The lists that were valid during the creation were used as basis.         Exposure controls         Personal protective equipment:         General protective and hygienic measures:         Wash hands before breaks and at the end of work.         Do not inhale dust / smoke / mist.         Protection of hands:         Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves         The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed Eye protection: Safety glasses         Physical and chemical properties         General Information         Appearance:         Form:       Powder         Color:       Black         Odor:       Odorless		
Additional Occupational Exposure Limit Values for possible hazards during processing:         USA OSHA (TWA/PEL): 15 mg/m3 (Total Dust), 5 mg/m3 (Respirable Fraction)         ACGIH (TWA/TLV): 10 mg/m3 (Inhalable Particulate), 3 mg/m3 (Respirable Particulate)         Amorphous Silica: USA OSHA (TWA/PEL): 20mppef 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3         TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion)         UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust)         Additional information: The lists that were valid during the creation were used as basis.         Exposure controls         Personal protective equipment:         General protective and hygienic measures:         Wash hands before breaks and at the end of work.         Do not inhale dust / smoke / mist.         Protection of thands:         Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation         Material of gloves         The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and from manufacturer.         Penetration time of glove material         The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed         Eye protection: Safety glasses         Information on basic physical and chemical properties         General Information         Appearanc		
USA OSHA (TWA/PEL): 15 mg/m3 (Total Dust), 5 mg/m3 (Respirable Fraction) ACGIH (TWA/TLV): 10 mg/m3 (Inhalable Particulate), 3 mg/m3 (Respirable Particulate) Amorphous Silica: USA OSHA (TWA/PEL): 20mppef 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3 TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion) UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust) Additional information: The lists that were valid during the creation were used as basis. Exposure controls Personal protective equipment: General protective equipment: General protective equipment: Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed Eye protection: Safety glasses Physical and chemical properties General Information Appearance: Form: For		I wit Values for possible becaude during processings
Amorphous Silica: USA OSHA (TWA/PEL): 20mppcf 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3 TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion) UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust) • Additional information: The lists that were valid during the creation were used as basis. • Exposure controls • Personal protective equipment: • General protective and hygienic measures: Wash hands before breaks and at the end of work. Do not inhale dust / smoke / mist. • Protection of hands: Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation • Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and from manufacturer to manufacturer. • Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed • Eye protection: Safety glasses • Information on basic physical and chemical properties • General Information • Appearance: Form: Powder Color: Black • Odor: Odorless		
TRGS 900 (Luftgrenzwert): 10 mg/m3 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion) UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust) Additional information: The lists that were valid during the creation were used as basis. Exposure controls Personal protective equipment: General protective and hygienic measures: Wash hands before breaks and at the end of work. Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed Eye protection: Safety glasses Information on basic physical and chemical properties General Information Appearance: Form: Powder Color: Dout manufacture: Powder Color: Dout material Physical and chemical properties Powder Color: Dout Black Odor: Dout material Physical and chemical properties Powder Physical and chemical properties Powder Po	ACGIH (TWA/TLV): 10 mg/m3 (Inh	nalable Particulate), 3 mg/m3 (Respirable Particulate)
UK WEL: 10 mg/m3 (Respirable Dust) 5 mg/m3 (Inhalible Dust) Additional information: The lists that were valid during the creation were used as basis. Exposure controls Personal protective equipment: General protective and hygienic measures: Wash hands before breaks and at the end of work. Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed Eye protection: Safety glasses Physical and chemical properties General Information Appearance: Form: Color: Oddriess	Amorphous Silica: USA OSHA (TW	/A/PEL): 20mppcf 80 mg/m3, ACGIH (TWA/TLV): 10 mg/m3
Additional information: The lists that were valid during the creation were used as basis.  Exposure controls Personal protective equipment: General protective and hygienic measures: Wash hands before breaks and at the end of work. Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation Material of gloves The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed Eye protection: Safety glasses  Physical and chemical properties Information Appearance: Form: Color: Black Oddor: Oddorless	TRGS 900 (Luftgrenzwert): 10 mg/m	13 (Einatembare partikel)). 3 mg/m3 (Alveolengängige fraktion)
Personal protective equipment:         General protective and hygienic measures:         Wash hands before breaks and at the end of work.         Do not inhale dust / smoke / mist.         Protection of hands:         Selection of the glove material on consideration of the penetration times, rates of diffusion and the degradation         Material of gloves         The selection of the suitable gloves does not only depend on the material, but also on further marks of quality and from manufacturer to manufacturer.         Penetration time of glove material         The exact break through time has to be found out by the manufacturer of the protective gloves and has to be observed         Eye protection: Safety glasses         Physical and chemical properties         General Information         Appearance:         Form:       Powder         Color:       Black         Odor:       Odorless		
<ul> <li>Information on basic physical and chemical properties</li> <li>General Information</li> <li>Appearance:         <ul> <li>Form:</li> <li>Powder</li> <li>Color:</li> <li>Black</li> <li>Odor:</li> <li>Odorless</li> </ul> </li> </ul>	Wash hands before breaks and at the Do not inhale dust / smoke / mist. Protection of hands:	end of work.
· General Information       · Appearance:       Form:     Powder       Color:     Black       · Odor:     Odorless	Wash hands before breaks and at the o Do not inhale dust / smoke / mist. <b>Protection of hands:</b> Selection of the glove material on cor <b>Material of gloves</b> The selection of the suitable gloves of from manufacturer to manufacturer. <b>Penetration time of glove material</b> The exact break through time has to b	end of work. nsideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari
Form:     Powder       Color:     Black       Odor:     Odorless	Wash hands before breaks and at the of Do not inhale dust / smoke / mist. <b>Protection of hands:</b> Selection of the glove material on correst of the gloves of the suitable gloves of the suitable gloves of the suitable gloves of the manufacturer to manufacturer. <b>Penetration time of glove material</b> The exact break through time has to be <b>Eye protection:</b> Safety glasses	end of work. nsideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.
Color:     Black       Odor:     Odorless	Wash hands before breaks and at the of Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on cor Material of gloves The selection of the suitable gloves of from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to b Eye protection: Safety glasses Physical and chemical proper Information on basic physical and of General Information	end of work. nsideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.
	Wash hands before breaks and at the of Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on cor Material of gloves The selection of the suitable gloves of from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to b Eye protection: Safety glasses Physical and chemical proper Information on basic physical and of General Information Appearance:	end of work.  Insideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.  Tries chemical properties
Odor threshold: Not determined.	Wash hands before breaks and at the of Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on cor Material of gloves The selection of the suitable gloves of from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to b Eye protection: Safety glasses Physical and chemical proper Information on basic physical and of General Information Appearance: Form:	end of work.  Insideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.
	Wash hands before breaks and at the or Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on cor Material of gloves The selection of the suitable gloves of from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to b Eye protection: Safety glasses Physical and chemical proper Information on basic physical and of General Information Appearance: Form: Color:	end of work.  Insideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.
<b>pH-value:</b> Not applicable.	Wash hands before breaks and at the or Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on cor Material of gloves The selection of the suitable gloves of from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to b Eye protection: Safety glasses Physical and chemical proper Information on basic physical and of General Information Appearance: Form: Color: Odor:	end of work.  nsideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.  rties chemical properties Powder Black Odorless
Change in condition	Wash hands before breaks and at the of Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on cor Material of gloves The selection of the suitable gloves of from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to b Eye protection: Safety glasses Physical and chemical proper Information on basic physical and of General Information Appearance: Form: Color: Odor: Odor threshold:	end of work.  Insideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.
	Wash hands before breaks and at the or Do not inhale dust / smoke / mist. Protection of hands: Selection of the glove material on correst Material of gloves The selection of the suitable gloves of from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to be Eye protection: Safety glasses Physical and chemical proper Information on basic physical and of General Information Appearance: Form: Color: Odor: Odor threshold: pH-value:	end of work.  Insideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.
vietung point/vietung range: Undetermined.	Wash hands before breaks and at the original properties the selection of hands: Selection of the glove material on constant of gloves of the suitable gloves of the suitable gloves of the selection time of glove material. The exact break through time has to be Eye protection: Safety glasses Physical and chemical proper Information on basic physical and of General Information Appearance: Form: Color: Odor: Odor threshold: pH-value: Change in condition	end of work.  Insideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.
	ash hands before breaks and at the operation of inhale dust / smoke / mist. <b>Sotection of hands:</b> lection of the glove material on con- <b>aterial of gloves</b> the selection of the suitable gloves of the selection of the suitable gloves of the manufacturer to manufacturer. <b>Exact break through time has to b</b> the exact break through time has to b the protection: Safety glasses <b>hysical and chemical proper</b> <b>formation on basic physical and of</b> <b>eneral Information</b> <b>opearance:</b> Form: Color: <b>dor threshold:</b> <b>I-value:</b> <b>hange in condition</b>	end of work.  Insideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and var be found out by the manufacturer of the protective gloves and has to be observed.  Tries  Chemical properties  Powder Black Odorless Not determined. Not applicable.
Melting point/Melting range:       Undetermined.         Boiling point/Boiling range:       Undetermined.	Wash hands before breaks and at the oponot inhale dust / smoke / mist. Protection of hands: Selection of the glove material on condition of the solution of the suitable gloves of from manufacturer to manufacturer. Penetration time of glove material The exact break through time has to be Eye protection: Safety glasses Physical and chemical proper Information on basic physical and of General Information Appearance: Form: Color: Odor: Odor threshold: pH-value: Change in condition Melting point/Melting range:	end of work.  Insideration of the penetration times, rates of diffusion and the degradation does not only depend on the material, but also on further marks of quality and vari be found out by the manufacturer of the protective gloves and has to be observed.



Safety Data Sheet acc. to OSHA HCS

Printing date 10/01/2020

Reviewed on 11/16/2017

### Trade name: Elevate Imaging Compatible Replacement Toner Cartridge for: HP® CE400X (BLACK)

	(Contd. of page
· Flash point:	Not applicable.
· Flammability (solid, gaseous):	Not determined.
· Ignition temperature:	>300 °C (>572 °F)
· Decomposition temperature:	Not determined.
· Auto igniting:	Product is not selfigniting.
· Danger of explosion:	Product does not present an explosion hazard in its original state.
· Explosion limits:	
Lower:	Not determined.
Upper:	Not determined.
· Vapor pressure:	Not applicable.
· Density:	SG: 1.3-1.8
· Relative density	Not determined.
· Vapor density	Not applicable.
· Evaporation rate	Not applicable.
· Solubility in / Miscibility with	
Water:	Insoluble.
· Partition coefficient (n-octanol/wa	ter): Not determined.
· Viscosity:	
Dynamic:	Not applicable.
Kinematic:	Not applicable.
· Solvent content:	
VOC content:	0.00 %
Solids content:	100.0 %
· Other information	No further relevant information available.

## 10 Stability and reactivity

· Reactivity Non reactive.

· Chemical stability

· Thermal decomposition / conditions to be avoided: No decomposition if used according to specifications.

- · Possibility of hazardous reactions No dangerous reactions known.
- · Conditions to avoid No further relevant information available.
- · Incompatible materials: No further relevant information available.
- · Hazardous decomposition products: No dangerous decomposition products known.

(Contd. on page 6)



Page 6/8

## Safety Data Sheet acc. to OSHA HCS

Printing date 10/01/2020

#### Reviewed on 11/16/2017

Trade name: Elevate Imaging Compatible Replacement Toner Cartridge for: HP® CE400X (BLACK)

(Contd. of page 5)

2B

3

# **11 Toxicological information**

· Information on toxicological effects

- Acute toxicity:
- · Primary irritant effect:
- on the skin: No toxic irritating effect, according to Directive 67/548/EEC or Directive 199/45/EC.
- on the eye: No toxic irritating effect, according to Directive 67/548/EEC or Directive 199/45/EC.
- Sensitization: No toxic sensitizing effects known, according to EU Directive 67/548/EEC or Directive 199/45/EC.
- Other information (about experimental toxicology):
- Mutagenicity : Ames test Negative (According to the test result of similar composition.)
- · Additional toxicological information:

The product is not subject to classification according to internally approved calculation methods for preparations: When used and handled according to specifications, the product does not have any harmful effects according to our experience and the information provided to us.

· Carcinogenic categories

### · IARC (International Agency for Research on Cancer)

Only unbound carbon black considered a Group 2 Carcinogen by IARC

1333-86-4 Carbon black (bound)

7631-86-9 silicon dioxide, chemically prepared

#### · NTP (National Toxicology Program)

None of the ingredients is listed.

### · OSHA-Ca (Occupational Safety & Health Administration)

None of the ingredients is listed.

## **12 Ecological information**

- · Toxicity
- · Aquatic toxicity: No further relevant information available.
- · Persistence and degradability No further relevant information available.
- Behavior in environmental systems:
- · Bioaccumulative potential No further relevant information available.
- · Mobility in soil No further relevant information available.
- · Additional ecological information:
- General notes: Not hazardous for water.
- · Results of PBT and vPvB assessment
- **PBT:** Not applicable.
- **vPvB:** Not applicable.
- · Other adverse effects No further relevant information available.

# **13 Disposal considerations**

- · Waste treatment methods
- · Recommendation: Smaller quantities can be disposed of with household waste.

(Contd. on page 7)

s —



Safety Data Sheet acc. to OSHA HCS

Printing date 10/01/2020

Reviewed on 11/16/2017

(Contd. of page 6)

Trade name: Elevate Imaging Compatible Replacement Toner Cartridge for: HP® CE400X (BLACK)

· Uncleaned packagings:

• Recommendation: Disposal must be made according to official regulations.

4 Transport information	
· UN-Number	Not a regulated material under the United States DOT, IMDG, ADR, RID, o ICAO/IATA.
<sup>·</sup> DOT, ADR, ADN, IMDG, IATA	Void
· UN proper shipping name	Not a regulated material under the United States DOT, IMDG, ADR, RID, CICAO/IATA
· DOT, ADR, ADN, IMDG, IATA	Void
· Transport hazard class(es)	Not a regulated material under the United States DOT, IMDG, ADR, RID, ICAO/IATA.
· DOT, ADR, ADN, IMDG, IATA	
·Class	Void
· Packing group	Not a regulated material under the United States DOT, IMDG, ADR, RID, ICAO/IATA.
· DOT, ADR, IMDG, IATA	Void
· Environmental hazards:	Not applicable.
· Special precautions for user	Not applicable.
· Transport in bulk according to Annex	
MARPOL73/78 and the IBC Code	Not applicable.
· UN "Model Regulation":	Void

# **15 Regulatory information**

• Safety, health and environmental regulations/legislation specific for the substance or mixture No further relevant information available.

· Sara

· Section 355 (extremely hazardous substances):

None of the ingredients is listed.

· Section 313 (Specific toxic chemical listings):

None of the ingredients is listed.

• **TSCA (Toxic Substances Control Act):** All components have the value ACTIVE.

· Hazardous Air Pollutants

None of the ingredients is listed.

· Proposition 65

### · Chemicals known to cause cancer:

1333-86-4 Carbon black (bound)

Page 7/8



### Safety Data Sheet acc. to OSHA HCS

Printing date 10/01/2020

#### Reviewed on 11/16/2017

Trade name: Elevate Imaging Compatible Replacement Toner Cartridge for: HP® CE400X (BLACK)

(Contd. of page 7)

A4

· Chemicals known to cause reproductive toxicity for females:

None of the ingredients is listed.

· Chemicals known to cause reproductive toxicity for males:

None of the ingredients is listed.

· Chemicals known to cause developmental toxicity:

None of the ingredients is listed.

· Carcinogenic categories

· EPA (Environmental Protection Agency)

None of the ingredients is listed.

· TLV (Threshold Limit Value established by ACGIH)

1333-86-4 Carbon black (bound)

· NIOSH-Ca (National Institute for Occupational Safety and Health)

1333-86-4 Carbon black (bound)

· GHS label elements The product is classified and labeled according to the Globally Harmonized System (GHS).

· Hazard pictograms Void

· Signal word Warning

· Hazard statements

May form combustible dust concentrations in air.

• Chemical safety assessment: A Chemical Safety Assessment has not been carried out.

## 16 Other information

This information is based on our present knowledge. However, this shall not constitute a guarantee for any specific product features and shall not establish a legally valid contractual relationship.

### $\cdot$ Date of preparation / last revision 10/01/2020 / -

· Abbreviations and acronyms:

ADR: Accord européen sur le transport des marchandises dangereuses par Route (European Agreement concerning the International Carriage of Dangerous Goods by Road) IMDG: International Maritime Code for Dangerous Goods DOT: US Department of Transportation IATA: International Air Transport Association ACGIH: American Conference of Governmental Industrial Hygienists EINECS: European Inventory of Existing Commercial Chemical Substances ELINCS: European List of Notified Chemical Substances CAS: Chemical Abstracts Service (division of the American Chemical Society) NFPA: National Fire Protection Association (USA) HMIS: Hazardous Materials Identification System (USA) VOC: Volatile Organic Compounds (USA, EU) PBT: Persistent, Bioaccumulative and Toxic vPvB: very Persistent and very Bioaccumulative NIOSH: National Institute for Occupational Safety OSHA: Occupational Safety & Health TLV: Threshold Limit Value PEL: Permissible Exposure Limit REL: Recommended Exposure Limit \* \* Data compared to the previous version altered. No changes to the Material Safety Data Sheet, all sections are current as the date of print seen above describes.

Page 8/8